



WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address Rt. 220/28	Common/Historic Name/Both X O O Marvin Chapel UM Church	Field Survey # HM-1191	Site # (SHPO Only) see also HM-0090-0001
Town or Community Purgitsville vicinity	County Hampshire	Negative No. WV_Hampshire County_HM-1191.tif	NR Listed Date
Architect/Builder Unknown	Date of Construction Circa 1920	Style Gothic	
Exterior Siding/Materials Aluminum, wood, glass	Roofing Material Metal	Foundation Block	
Property Use or Function Residence O Commercial O Other X Church	NAD 83 UTM# 17S 0679420E/ 4346000N		
Survey Organization & Date Rasmussen and Rasmussen Fall 2010	Quadrangle Name Old Fields		
	Part of What Survey Hampshire County Phase III		

erty
USGS Map

Site No.

Present Owners Stump, Jodi, pastor Phone #	Owners Mailing Address								
Describe Setting Very close to the road surrounded by open meadow <1 ____ Acres ____ Artifacts Present									
Description of Building or Site (Original and Present) 1 Stories ____ 3 ____ Front Bays Center hall, double doors with transom over, flanked by 1/1 double hung Gothic windows. Gable front with Gothic triangular window over entry system. Wide eave overhang, steep roof pitch. Right rear shed roofed winglet with entrance, one story rear extension <i>(Use Continuation Sheets)</i>									
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%; text-align: center;"> ☒ </td> <td style="width: 10%; text-align: center;"> ☐ </td> <td style="width: 65%;">If yes, describe Aluminum siding</td> </tr> <tr> <td></td> <td style="text-align: center;">Yes</td> <td style="text-align: center;">No</td> <td></td> </tr> </table>		Alterations	☒	☐	If yes, describe Aluminum siding		Yes	No	
Alterations	☒	☐	If yes, describe Aluminum siding						
	Yes	No							
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%; text-align: center;"> ☒ </td> <td style="width: 10%; text-align: center;"> ☐ </td> <td style="width: 65%;">Rear Extension</td> </tr> <tr> <td></td> <td style="text-align: center;">Yes</td> <td style="text-align: center;">No</td> <td></td> </tr> </table>		Additions	☒	☐	Rear Extension		Yes	No	
Additions	☒	☐	Rear Extension						
	Yes	No							
Describe All Outbuildings None <i>(Use Continuation Sheets)</i>									
Statement of Significance Building retains its architectural integrity <i>(Use Continuation Sheets)</i>									
Bibliographical References <i>(Use Continuation Sheets)</i>									
<table style="width: 100%; border: none;"> <tr> <td style="width: 70%;"> Form Prepared By: Barbara Rasmussen 2010 Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652 </td> <td style="width: 30%; vertical-align: top;"> Date: October 13, 2010, </td> </tr> </table>		Form Prepared By: Barbara Rasmussen 2010 Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652	Date: October 13, 2010,						
Form Prepared By: Barbara Rasmussen 2010 Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652	Date: October 13, 2010,								



West Virginia Division of Culture and History
 State Historic Preservation Office

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.



Internal Rating: NE

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

see also HM-1191

Street Address US Route 220	Common/Historic Name/Both ☐ ☐ Marvin Chapel ☒	Field Survey # 0001	Site # (SHPO Only) HM-0090- 0001
Town or Community Purgitsville	County Hampshire	Negative No.	NR Listed Date
Architect/Builder Unknown	Date of Construction circa 1895	Style (SHPO Only) Gothic Revival	
Exterior Siding / Materials Vinyl siding	Roofing Material Rolled-Synthetic Material metal	Foundation Unknown	
Property Use or Function Religious	UTM Zone 17 NAD 1927 Easting 679,400 Northing 4,345,783	Photograph (2" x 3" Contact)	
Survey Organization & Date WVDOH September 14, 2000	Quadrangle Name Old Fields		
	Part of What Survey / FR#		



GM

HM-0090-0001

Site No.

Name: Marvin Chapel

Survey #:

Survey / FR#:

HM-1090-0001

Present Owners Unknown	Owners Mailing Address Unknown
Describe Setting - <1 Acres ☐ Archaeological Artifacts Present Marvin Chapel is situated in a rural setting on the east side of State Route 220. It is approximately .5 miles North of Purgitsville	
Description of Buildings or Site (Original and Present) 1 Stories 2 Front Bays The Marvin Chapel has a gabled roof with snowshoes. Double hung, double sashed, multi-paned, lancet Arch windows; two in front three on each side. Double doors with a transom window, and a triangular shaped mid-gabled window above the door..	
Alterations ☒ Yes ☐ No If yes, describe Addition of Vinyl siding.	
Additions ☐ Yes ☒ No If yes, describe	
Describe All Outbuildings	
Statement of Significance: See Continuation Sheet	
Bibliographical References McAlester, V. and L. 1984. A Field Guide to American Houses. NY: Alfred A. Knopf	
Form Prepared By: Date: September 14, 2000 Name/Organization: Chandra Inglis Address: WV Division of Highways Capitol Complex Building 5, Rm. 463 Charleston, WV 25305 Phone #: 558-2885	

WEST VIRGINIA HISTORIC PROPERTY FORM CONTINUATION SHEET

Name: Marvin Chapel
Survey Number:
Project / FR#:

As an individual structure, the church does not have an important link with events or trends that have made a significant contribution to the broad patterns of our history. As an individual structure it does not meet National Register Criteria A of association with events at the National, Regional, or Local level.

It is not eligible for the National Register because it is not known to have been associated with the productive period of some notable person's life, nor has it been associated for any length of time with such a person, nor is it the best representation of such a person's historic contribution (NRHP Criterion B).

This structure does not represent the work of a master or possess high artistic values. While it embodies the characteristics of an architectural period, they are of commonplace type and method of construction, and this is not an important example of these building practices. Its workmanship is not remarkable. NRHP Criterion C is not met by this structure.

This structure is not likely to have important information that will contribute to our understanding of human history or prehistory. Construction appears to have utilized known techniques, tools, and materials. The potential for information is trivial, so NRHP Criterion D is not met.