




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address W side Rock Oak Road c. .1 mi. S of Grassy Lick Road	Common/Historic Property Name/ Both Bethel Baptist Church (historic)	Field Survey # Central Hampshire County Survey No. 86	Site # (SHPO Only) Hm-0890
Town or Community Kirby	County Hampshire	Image No. 3380	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1870	Style temple-form; Italianate (elements)	
Exterior Siding/Materials Vinyl over Weatherboard	Roofing Material Standing-Seam Metal	Foundation Concrete Block	
Property Use or Function Other/Religious Use	UTM # 17/4329207/696333		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	Acres
This property lies along a county road in rural south-central Hampshire County, in the unincorporated crossroads village of Kirby. Its associated cemetery (Survey Site No. XXX) is adjacent to the south.	
none Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	1 Stories 6 Front Bays
1-story religious building of wood construction with a temple-form façade, incorporating a centered double door accessed from a non-historic wood stoop. Full return of the cornice on the façade, with modillions under the eaves. 3-bay side elevations with flat topped windows and multi-light replacement sash. A 1-story gable-end oriented addition has been built on the rear.	
(Use Continuation Sheets)	
Alterations	☒ Yes ☐ No If yes, describe Non-historic siding; replacement windows; foundation replaced
Additions	☒ Yes ☐ No If yes, describe A non-historic addition has been built onto the rear elevation.
Describe all Outbuildings	
None	
(Use Continuation Sheets)	
Statement of Significance:	
This church has been altered with non-historic siding and window replacements, and does not appear to meet National Register Criteria for Evaluation	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By:	
Date: July 2009	
Name/Organization:	David L. Tavor. Principal. Tavor and Tavor Associates. Inc.
Address:	9 Walnut Street Brookville, PA 15825
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com

West Virginia Division of Culture and History
State Historic Preservation Office