



Internal Rating: NE

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address 3236 Northwestern Pike	Common/Historic Name/Both ☐ ☐ ☒ Capon Bridge United Methodist Church	Field Survey #	Site # (SHPO Only) HM-1415
Town or Community Capon Bridge	County Hampshire	Negative No.	NR Listed Date
Architect/Builder unknown	Date of Construction ca. 1870	Style Gothic Revival	
Exterior Siding/Materials Wood siding	Roofing Material Slate and standing seam metal	Foundation Coursed ashlar	
Property Use or Function Residence ☐ Commercial ☐ Other ☒	UTM# 17N 721017E 4353114N		
Survey Organization & Date TRC Environmental Corp. June 2016	Quadrangle Name Capon Bridge		
	Part of What Survey/FR# FR;16-945-HM		

Sketch Map of Property
Or Attach Conv of USGS Map



Site No.

Present Owners N/A Phone #	Owners Mailing Address								
Describe Setting 1 Acres The Capon Bridge United Methodist Church is located at the northwest corner U.S. Route 50 and SR 15, Cold Stream Road. A coursed stone wall separates the church from U.S. Route 50. Archaeological Artifacts Present									
Description of Building or Site (Original and Present) 2 Stories 3 Front Bays The Capon Bridge United Methodist Church is set on a coursed ashlar foundation. The four-part hexagonal steeple is attached to a two story, three-bay auditorium. A two-story, three bay classroom addition has been added to the rear of the auditorium. The double-leaf, door is topped by a half-round transom and positioned at the center of the steeple. Above the door is a round window. The first two section of the steeple are clad in wood siding. The third section is covered in fish scale wood shingles and an enclosed window pierces each of the six sides of the steeple. The conical roof of the steeple, which is the fourth section, is clad in square and fish scale slate shingles and boasts three narrow front gable dormer windows. The two fixed sash windows, one on each story, flank the steeple in the façade. Three one-over-one, wood-sash windows pierce the east and west elevations of the auditorium. <i>(Use Continuation Sheets)</i>									
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%; vertical-align: top;">Alterations</td> <td style="width: 10%; text-align: center;"> ☒ </td> <td style="width: 10%; text-align: center;"> ☐ </td> <td style="width: 65%; vertical-align: top;"> If yes, describe: The windows in the third section of the steeple have been enclosed </td> </tr> <tr> <td></td> <td style="text-align: center;">Yes</td> <td style="text-align: center;">No</td> <td></td> </tr> </table>		Alterations	☒	☐	If yes, describe: The windows in the third section of the steeple have been enclosed		Yes	No	
Alterations	☒	☐	If yes, describe: The windows in the third section of the steeple have been enclosed						
	Yes	No							
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%; vertical-align: top;">Additions</td> <td style="width: 10%; text-align: center;"> ☒ </td> <td style="width: 10%; text-align: center;"> ☐ </td> <td style="width: 65%; vertical-align: top;"> If yes, describe: A two-story, three bay classroom addition has been added to the rear of the auditorium. </td> </tr> <tr> <td></td> <td style="text-align: center;">Yes</td> <td style="text-align: center;">No</td> <td></td> </tr> </table>		Additions	☒	☐	If yes, describe: A two-story, three bay classroom addition has been added to the rear of the auditorium.		Yes	No	
Additions	☒	☐	If yes, describe: A two-story, three bay classroom addition has been added to the rear of the auditorium.						
	Yes	No							
Describe All Outbuildings There are no outbuildings associated with this church. <i>(Use Continuation Sheets)</i>									
Statement of Significance The Capon Bridge United Methodist Church is not associated with significant events or persons within the broad patterns of history on the local, state, or national level and is not eligible for the National Register under Criterion A or B. The church has been altered and does not embody the distinctive characteristics of a type, period, or method of construction, nor is it the work of a known architect or builder, and is not eligible for the National Register under Criterion C. Eligibility under Criterion D was not investigated as part of this study. <i>(Use Continuation Sheets)</i>									
Bibliographical References <i>(Use Continuation Sheets)</i>									
<table style="width: 100%; border: none;"> <tr> <td style="width: 70%;"> Form Prepared By: Stephanie A.T. Jacobs, Ph.D. </td> <td style="width: 30%;"> Date: 07/21/2016 </td> </tr> <tr> <td colspan="2" style="padding-top: 10px;"> Name/Organization: TRC Environmental Corp. Address: 4425 Forbes Blvd., Suite B Lanham MD 20706 Phone #: 301-276-8043 </td> </tr> </table>		Form Prepared By: Stephanie A.T. Jacobs, Ph.D.	Date: 07/21/2016	Name/Organization: TRC Environmental Corp. Address: 4425 Forbes Blvd., Suite B Lanham MD 20706 Phone #: 301-276-8043					
Form Prepared By: Stephanie A.T. Jacobs, Ph.D.	Date: 07/21/2016								
Name/Organization: TRC Environmental Corp. Address: 4425 Forbes Blvd., Suite B Lanham MD 20706 Phone #: 301-276-8043									



West Virginia Division of Culture and History
State Historic Preservation Office

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.

WEST VIRGINIA HISTORIC PROPERTY FORM

CONTINUATION SHEET

NAME__ Capon Bridge United Methodist Church _____ SITE#_____HM-1415_____



View of the Capon Bridge United Methodist Church looking north



View of the Capon Bridge United Methodist Church looking west

WEST VIRGINIA HISTORIC PROPERTY FORM

CONTINUATION SHEET

NAME__ Capon Bridge United Methodist Church _____ SITE#_____HM-1415_____



View of the Capon Bridge United Methodist Church ca. 1900