



WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address CR 8 River Road	Common/Historic Name/Both x O O Parker-Scanlon house	Field Survey # HM-1308	Site # (SHPO Only) HM-0077
Town or Community River Road vicinity	County Hampshire	Negative No. WV_HampshireCounty_HM-1308.tif	NR Listed Date
Architect/Builder unknown	Date of Construction Circa 1800	Style I house with extensions	
Exterior Siding/Materials Wood	Roofing Material Metal	Foundation Stone	
Property Use or Function Residence X Commercial O Other O	NAD83 UTM# 17S 0691710E/4356243N		
Survey Organization & Date Rasmussen and Rasmussen Fall 2010	Quadrangle Name Romney		
	Part of What Survey Western Hampshire County		

Sketch Map of Property
Or Attach Copy of USGS Map

Site No.

Present Owners Phone #	Owners Mailing Address
Describe Setting Farm above the road grade. ~100 ____ Acres ____ Artifacts Present	
Description of Building or Site (Original and Present) 2 Stories 3 Front Bays Center hall, 1/1 double hung sash wide window trim, interior brick chimney, low hipped porch roof with four Doric columns and no railing. Two story rear extension and one story rear extension that is likely to be log construction.	
<i>Use Continuation Sheets)</i>	
☐ Yes ☒ No	
Additions ☒ Yes ☐ No Extensions are historic	
Describe All Outbuildings One large wooden barn with hay hood, one chicken house, one machine shed, all of wood with pole foundations, all C <i>(Use Continuation Sheets)</i>	
Statement of Significance Association with agricultural traditions, architecture. Individually eligible for the National Register Criteria A and C. <i>(Use Continuation Sheets)</i>	
Bibliographical References <i>(Use Continuation Sheets)</i>	
Form Prepared By: Barbara Rasmussen Date: November 24, 2010 Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652	



West Virginia Division of Culture and History
State Historic Preservation Office

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.

DEPARTMENT OF CULTURE & HISTORY
THE CULTURAL CENTER
CHARLESTON, WEST VIRGINIA 25305

RATING NR CHD
CONTEXT APL CH

UTM Ref:

USGS Quad:

Neg No(s):

Theme(s):

File No:

DISTRICT...SITE...BUILDING...STRUCTURE...OBJECT

1. NAME(S), historic/common:

Parker-Scanlon Home

2. LOCATION,

street/road: Along the east side of
River Road, 1 mile south of
city/town: Romney, WV
(incorporated/unincorporated)

HM-0077

3. USE/FUNCTION,

present: Private home

(public/private)
restricted)

original: Settlers' home (?)
Tenant house

4. OWNER/ADDRESS,


present: Mrs. A. C. Scanlon
Romney, WV

(public/private)

original: unknown

5. PHOTO/SKETCH OF:

7. PLAN (include approx. dimensions):



33' x 70'

6. LOCALE/ENVIRONMENT(map):

No. 15a on map

8. ACREAGE (approx):
200

NM

Survey Region: _____
Planning District: _____

COUNTY: HAMPSHIRE

APR 1982

a. Exterior Fabric

stone _____
 brick _____
 concrete _____
 stucco _____
 weatherboard X German
 clapboard _____
 board & batten _____
 shingle _____
 other _____

b. Structural System

masonry _____
 frame X West addit'n
 log X Central section
 metal _____
 other _____
 foundation Stone
Cellar under
one room of addt'n.

c. Roofing Material

wood _____
 metal X Stand. seam
 slate _____
 tile _____
 asphalt _____
 composition _____
 other _____

d. Associated Structures (use/type):

outbuildings Blacksmith shop c.1903
Barn 1910 signed & dated PHOTO
Granary c.1910
 dependencies _____
 other _____

e. Integrity (include dates):

original site/relocated Orig. site
 alterations _____
 additions Main house added to log
portion in 1903
Kitchen, ice house, dairy
added unknown time

f. Condition:

excellent _____
 good X _____
 fair _____
 deteriorated _____
 abandoned _____

g. Threats: None known

10. SIGNIFICANCE (use additional sheet if necessary):

a. Architect/Builder/Engineer:
James M. Parker
1903 addt'n.
 b. Style/Period:
Classic Revival
 c. Date(s):
1903

Original log portion of house is covered by modern siding; attic & crawlspace inaccessible as is orig. chimney. Cannot assess.

1903 addition together with outbuildings form a good example of an early 20th century self-sufficient farm.

11. BIBLIOGRAPHY:

Interview with Nelle Parker Scanlon

12. FORM PREPARED BY Eugene Williams : DATE 9-21-84
 a. Address _____
 b. Organization _____

WEST VIRGINIA HISTORIC PROPERTY FORM
CONTINUATION SHEET

NAME Parker-Scanlon Home

SITE #

WV 43 HM-0077

