

Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address Falling Leaf Road//WV Rt. 9	Common/Historic Name/Both ☒ ☐ ☐ Woodrow Union Church	Field Survey # HM-0150	Site # (SHPO Only) 10-012
Town or Community Rural	Hampshire	Negative No.	NR Listed Date
Architect/Builder	Date of Construction Circa 1900	Style Gothic	
Exterior Siding/Materials Wood, Aluminum	Roofing Material Standing seam metal	Foundation Stone veneer	
Property Use or Function Residence ☐ Commercial ☐ Other ☒ Church	UTM# 17 S 0720415E/ 4375085N		
Survey Organization & Date Barbara Rasmussen Fall 2008	Quadrangle Name Largent		
Part of What Survey Hampshire County			

Photograph

Sketch Map of Property
Or Attach Copy of USGS Map



Present Owners Phone #	Owners Mailing Address
Describe Setting Less than one acre Along WV Rt.9 at the intersection of Falling Leaf Road. Well maintained small church behind large paring lot. Low foundation plantings _____ Archaeological Artifacts Present	
Description of Building or Site (Original and Present) _____ 1 _____ Stories 4 _____ Front Bays Metal roof, stone veneer foundation. Gothic windows with decorative stylized shutters. Left side ell extension with second entry. Original 2/2 double hung sash with pointed arch above, Masonry stairs with metal handrails. Snowbirds on roof. Well maintained and updated older church. (Use Continuation Sheets)	
Alterations ☒ Yes ☐ No If yes, describe Aluminum siding	
Additions ☐ Yes ☒ No If yes, describe	
Describe All Outbuildings (Use Continuation Sheets)	
Statement of Significance Gothic architectural elements (Use Continuation Sheets)	
Bibliographical References (Use Continuation Sheets)	
Form Prepared By: Date: August 31, 2008 Barbara Rasmussen Name/Organization: Historic Preservation and Research Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652	

