




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address W side Harmison Road, c. .1 mi. SW of Augusta	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 43	Site # (SHPO Only) Hm-0847
Town or Community Augusta	County Hampshire	Image No. 3287	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1940	Style Cape Cod	
Exterior Siding/Materials Asbestos shingles	Roofing Material Asphalt Shingles	Foundation Parged	
Property Use or Function Residence	UTM # 17/4351686/703244		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Augusta, WV Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address								
Phone #									
Describe Setting									
This property lies along a county road in rural Hampshire County, in the unincorporated village of Augusta. Acres none									
Archaeological Artifacts Present none									
Description of Buildings or Site (Original and Present)									
1½ Stories 3 Front Bays									
1½-story Cape Cod-style residence of wood construction, with a side gable roof and paired gable dormers on the façade. The first story is 3 bays in width, with the centered entrance which is shielded by a pedimented portico supported by plain wood posts. A 1-story addition or enclosed porch is on the rear. Fenestration is flat topped, 6/6, with replacement wood sash. A non-historic wood deck has been built onto the rear.									
(Use Continuation Sheets)									
<table style="width: 100%;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Asbestos shingle siding; replacement sash </td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe Asbestos shingle siding; replacement sash					
Alterations	☒ Yes ☐ No	If yes, describe Asbestos shingle siding; replacement sash							
<table style="width: 100%;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Deck on rear </td> </tr> </table>		Additions	☒ Yes ☐ No	If yes, describe Deck on rear					
Additions	☒ Yes ☐ No	If yes, describe Deck on rear							
Describe all Outbuildings									
(Use Continuation Sheets)									
Statement of Significance:									
This property is architecturally undistinguished and does not appear to meet National Register Criteria for Evaluation.									
(Use Continuation Sheets)									
Bibliographical References									
(Use Continuation Sheets)									
<table style="width: 100%;"> <tr> <td style="width: 50%;">Form Prepared By:</td> <td style="width: 50%;">Date: July 2009</td> </tr> <tr> <td>Name/Organization:</td> <td>David L. Taylor, Principal, Taylor and Taylor Associates, Inc.</td> </tr> <tr> <td>Address:</td> <td>9 Walnut Street Brookville, PA 15825</td> </tr> <tr> <td>Phone #:</td> <td>814-849-4900 email: david@taylorandtaylorassociates.com</td> </tr> </table>		Form Prepared By:	Date: July 2009	Name/Organization:	David L. Taylor, Principal, Taylor and Taylor Associates, Inc.	Address:	9 Walnut Street Brookville, PA 15825	Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com
Form Prepared By:	Date: July 2009								
Name/Organization:	David L. Taylor, Principal, Taylor and Taylor Associates, Inc.								
Address:	9 Walnut Street Brookville, PA 15825								
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com								

West Virginia Division of Culture and History
State Historic Preservation Office