





Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address W side Co. Rd. 12, c. .8 mi. S of US Rt. 50	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 59	Site # (SHPO Only) HM-0863
Town or Community vic. Augusta	County Hampshire	Image No. 3312	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style side-passage	
Exterior Siding/Materials Insul-brick	Roofing Material Asphalt Shingles	Foundation Not visible	
Property Use or Function Residence	UTM # 17/4351692/700360		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Augusta, WV		
	Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address								
Phone #									
Describe Setting									
This property lies along a county road in rural Hampshire County, west of the unincorporated village of Augusta.									
Acres none Archaeological Artifacts Present									
Description of Buildings or Site (Original and Present) <u>1</u> Stories <u>3</u> Front Bays									
1-story vernacular cottage of wood construction with a side gable roof and a 2-bay façade, with the main entrance offset, shielded by a shed-roofed porch which is supported by turned wood posts. Fenestration is flat topped, without notable ornament.									
(Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Insul-brick finishes added </td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe Insul-brick finishes added					
Alterations	☒ Yes ☐ No	If yes, describe Insul-brick finishes added							
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☐ Yes ☒ No </td> <td style="width: 75%;"> If yes, describe Not visible from the public right-of-way. </td> </tr> </table>		Additions	☐ Yes ☒ No	If yes, describe Not visible from the public right-of-way.					
Additions	☐ Yes ☒ No	If yes, describe Not visible from the public right-of-way.							
Describe all Outbuildings									
(Use Continuation Sheets)									
Statement of Significance:									
This property is architecturally undistinguished and does not appear to meet National Register Criteria for Evaluation.									
(Use Continuation Sheets)									
Bibliographical References									
(Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Form Prepared By:</td> <td style="width: 50%;">Date: July 2009</td> </tr> <tr> <td>Name/Organization:</td> <td>David L. Taylor. Principal. Taylor and Taylor Associates. Inc.</td> </tr> <tr> <td>Address:</td> <td>9 Walnut Street Brookville, PA 15825</td> </tr> <tr> <td>Phone #:</td> <td>814-849-4900 email: david@taylorandtaylorassociates.com</td> </tr> </table>		Form Prepared By:	Date: July 2009	Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.	Address:	9 Walnut Street Brookville, PA 15825	Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com
Form Prepared By:	Date: July 2009								
Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.								
Address:	9 Walnut Street Brookville, PA 15825								
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com								

West Virginia Division of Culture and History
State Historic Preservation Office