




Internal Rating: _____


WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Ash Ruckman Road, c. .2 mi. N of Cupps Hollow Road	Common/Historic Property Name/Both	Field Survey # Central Hampshire County Survey No. 74	Site # (SHPO Only) HM - 0878
Town or Community vic. Augusta	County Hampshire	Image No. 3350-3352	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials Weatherboard	Roofing Material Standing-Seam Metal	Foundation Not visible	
Property Use or Function Residence	UTM # 17/4344185/698185		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV		
Part of What Survey/FR# Central Hampshire County Historic Resource Survey			

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report


Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This property lies along a county road in rural Hampshire County, northwest of the unincorporated village of Augusta. Acres <u>none</u> Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
<u>2</u> Stories <u>3</u> Front Bays	
2-story vernacular residence of wood construction, with a side-gable roof and exterior gable-end stone and brick chimney. Exterior surfaces retain the original wood finishes. The main entrance is centered on the façade, and is shielded by a wraparound porch supported by Doric columns. Fenestration is flat topped, with windows set singly and in pairs. The original porch skirting and the foundation are covered in rock-faced pressed metal sheets. A 1-story porch with a shed roof, also supported by Doric columns, is on the side elevation.	
(Use Continuation Sheets)	
Alterations ☐ Yes ☒ No If yes, describe	
Additions ☐ Yes ☒ No If yes, describe	
Describe all Outbuildings	
Behind the subject property is a modestly-scaled dependency of wood construction finished in shiplap siding, with a standing-seam metal roof.	
(Use Continuation Sheets)	
Statement of Significance:	
This property is architecturally undistinguished, and does not appear to meet National Register Criteria for Evaluation.	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By: _____ Date: July 2009	
Name/Organization: David L. Taylor, Principal, Taylor and Taylor Associates, Inc.	
Address: 9 Walnut Street Brookville, PA 15825	
Phone #: 814-849-4900 email: david@taylorandtaylorassociates.com	

West Virginia Division of Culture and History
State Historic Preservation Office



Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Ash Ruckman Road, c. 2 mi. N of Cupps Hollow Road	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 74	Site # (SHPO Only) HM-0878
Town or Community vic. Augusta	County Hampshire	Image No. 3350-3352	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials Weatherboard	Roofing Material Standing-Seam Metal	Foundation Not visible	
Property Use or Function Residence	UTM # 17/4344185/698185		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV		
Part of What Survey/FR# Central Hampshire County Historic Resource Survey			

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This property lies along a county road in rural Hampshire County, northwest of the unincorporated village of Augusta. Acres <u>none</u> Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
<u>2</u> Stories <u>3</u> Front Bays 2-story vernacular residence of wood construction, with a side-gable roof and exterior gable-end stone and brick chimney. Exterior surfaces retain the original wood finishes. The main entrance is centered on the façade, and is shielded by a wraparound porch supported by Doric columns. Fenestration is flat topped, with windows set singly and in pairs. The original porch skirting and the foundation are covered in rock-faced pressed metal sheets. A 1-story porch with a shed roof, also supported by Doric columns, is on the side elevation. (Use Continuation Sheets)	
Alterations ☐ Yes ☒ No If yes, describe	
Additions ☐ Yes ☒ No If yes, describe	
Describe all Outbuildings	
Behind the subject property is a modestly-scaled dependency of wood construction finished in shiplap siding, with a standing-seam metal roof. (Use Continuation Sheets)	
Statement of Significance:	
This property is architecturally undistinguished, and does not appear to meet National Register Criteria for Evaluation. (Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By: _____ Date: July 2009	
Name/Organization: David L. Tavior. Principal. Tavior and Tavior Associates. Inc.	
Address: 9 Walnut Street Brookville, PA 15825	
Phone #: 814-849-4900 email: david@taylorandtaylorassociates.com	

West Virginia Division of Culture and History
State Historic Preservation Office

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Site Number 74

