




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Ben Saville Road, N of Kirby	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 81	Site # (SHPO Only) HM-0885
Town or Community vic. Kirby	County Hampshire	Image No. 3371-3373	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials Vinyl over Weatherboard	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence	UTM # 17/4340242/696800		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners

Owner's Mailing Address

Phone #

Describe Setting

Acres

This property lies along a county road in rural south-central Hampshire County,

none Archaeological
Artifacts Present

Description of Buildings or Site (Original and Present)

2 Stories

3 Front Bays

2-story central passage I-house of wood construction, with a side-gable roof and a double-gallery shed-roofed porch on the façade. The porch incorporates the original supports on the second story, but those of the first story and all of the balustrade have been replaced. A hipped-roof rear porch, with historic supports and balustrade. 3-bay façade on the main portion of the house, with some 2/2 sash remaining. Matching centered entries on both the first and second story open onto the porch.

(Use Continuation Sheets)

Alterations



If yes, describe

Yes

No

Non-historic siding; porch balustrade

Additions



If yes, describe

Yes

No

Describe all Outbuildings

Scattered around the property are a series of wood dependencies, some finished in vertical siding and one finished in insul-brick.

(Use Continuation Sheets)

Statement of Significance:

This property is architecturally undistinguished, has been altered with the modification of the porch railing, and does not appear to meet National Register Criteria for Evaluation.

(Use Continuation Sheets)

Bibliographical References

(Use Continuation Sheets)

Form Prepared By:

Date: July 2009

Name/Organization:

David L. Taylor, Principal, Taylor and Taylor Associates, Inc.

Address:

9 Walnut Street

Brookville, PA 15825

Phone #:

814-849-4900 email: david@taylorandtaylorassociates.com

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____

Survey Site Number _____

81

