




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address S side Grassy Lick Road, c. .3 mi. E of Kirby	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 91	Site # (SHPO Only) HM-0895
Town or Community vic. Kirby	County Hampshire	Image No. 3391-3393	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials Vinyl over Weatherboard	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence	UTM # 17/4338991/696897		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This property lies along a county road in rural south-central Hampshire County south of the unincorporated crossroads village of Kirby.	
Acres none Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
_____ 3 Stories _____ 4 Front Bays	
2-story vernacular residence of wood construction with gable roof and gable-end orientation, with a 2-bay façade, a side entry, and hipped-roof verandah extending across the façade and wrapping around a portion of the side elevation. Fenestration is flat topped, without notable ornament. In the pediment of the gable on the façade is a diamond-shaped window. Open back porch on the rear elevation. Closer inspection is precluded by "No Trespassing" signs.	
(Use Continuation Sheets)	
Alterations ☒ Yes ☐ No If yes, describe Non-historic siding; porch post replacements.	
Additions ☐ Yes ☐ No If yes, describe	
Describe all Outbuildings	
Several dependencies of varying scale, including barns and sheds are scattered around the property.	
(Use Continuation Sheets)	
Statement of Significance:	
This property is architecturally undistinguished, has undergone alterations, and does not appear to meet National Register Criteria for Evaluation.	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By: _____ Date: July 2009	
Name/Organization: David L. Tavor. Principal. Tavor and Tavor Associates. Inc.	
Address: 9 Walnut Street Brookville, PA 15825	
Phone #: 814-849-4900 email: david@taylorandtaylorassociates.com	

West Virginia Division of Culture and History
State Historic Preservation Office

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM CONTINUATION SHEET

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Survey Site Number 91



