




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address S. side Grassy Lick Road, c. .75 mi. N of Kirby	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 92	Site # (SHPO Only) Hm-0896
Town or Community vic. Kirby	County Hampshire	Image No. 3394-3396	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage I-house	
Exterior Siding/Materials Vinyl over Weatherboard	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence	UTM # 17/4341450/695895		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Rio, WV		
	Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address								
Phone #									
Describe Setting Acres This property lies along a county road in rural south-central Hampshire County south of the unincorporated crossroads village of Kirby. none Archaeological Artifacts Present									
Description of Buildings or Site (Original and Present) <u>2</u> Stories <u>2</u> Front Bays 2-story vernacular I-house of wood construction with a side-gable roof, 2-bay façade, and a shed-roofed front porch enclosed with jalousie windows. 1-story rearward-projecting ell. Fenestration is flat topped, with replacement sash. (Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Porch enclosed; non-historic siding; window replacement </td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe Porch enclosed; non-historic siding; window replacement					
Alterations	☒ Yes ☐ No	If yes, describe Porch enclosed; non-historic siding; window replacement							
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Addition on rear elevation </td> </tr> </table>		Additions	☒ Yes ☐ No	If yes, describe Addition on rear elevation					
Additions	☒ Yes ☐ No	If yes, describe Addition on rear elevation							
Describe all Outbuildings Domestic dependencies which include sheds and a spring house. (Use Continuation Sheets)									
Statement of Significance: This property is architecturally undistinguished, has undergone alterations, and does not appear to meet National Register Criteria for Evaluation. (Use Continuation Sheets)									
Bibliographical References (Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Form Prepared By:</td> <td style="width: 50%;">Date: July 2009</td> </tr> <tr> <td>Name/Organization:</td> <td>David L. Taylor. Principal. Taylor and Taylor Associates. Inc.</td> </tr> <tr> <td>Address:</td> <td>9 Walnut Street Brookville, PA 15825</td> </tr> <tr> <td>Phone #:</td> <td>814-849-4900 email: david@taylorandtaylorassociates.com</td> </tr> </table>		Form Prepared By:	Date: July 2009	Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.	Address:	9 Walnut Street Brookville, PA 15825	Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com
Form Prepared By:	Date: July 2009								
Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.								
Address:	9 Walnut Street Brookville, PA 15825								
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com								

West Virginia Division of Culture and History
State Historic Preservation Office

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM CONTINUATION SHEET

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Survey Site Number _____

