

Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address	**Common/Historic Property Name/ Both**	**Field Survey #**	**Site # (SHPO Only)**
S side Grassy Lick Road, c. 1 mi. N of Kirby		Central Hampshire County Survey No. 122	HM-0925
Town or Community	**County**	**Image No.**	**NR Listed Date**
vic. Kirby	Hampshire	3455-3457	n/a
Architect/Builder	**Date of Construction**	**Style**	
Unidentified	c. 1920		
Exterior Siding/Materials	**Roofing Material**	**Foundation**	
Vinyl over Weatherboard	Standing-Seam Metal	Stone	
Property Use or Function	**UTM #**		
Residence	17/4342778/694893		
Survey Organization and Date	**Quadrangle Name**		
Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Rio, WV		
	Part of What Survey/FR#		
	Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners | **Owner's Mailing Address**

Phone #

Describe Setting

This property lies on a county road, south of U. S. Rt. 50, in rural south-central Hampshire County, northwest of the unincorporated village of Kirby.

Acres

none **Archaeological Artifacts Present**

Description of Buildings or Site (Original and Present) 1½ **Stories** 3 **Front Bays**

1½ story vernacular cottage of wood construction, with a side gable-roof and a prominent centered gable on the façade with a single window set therein. Extending across the façade is a hipped-roof porch, supported by wrought iron posts. Exterior gable-end chimneys. Fenestration is flat topped, with windows set singly and in pairs, without notable architectural embellishment.

(Use Continuation Sheets)

Alterations ☑ Yes ☐ No **If yes, describe**
Porch supports changed; non-historic siding

Additions ☐ Yes ☐ No **If yes, describe**

Describe all Outbuildings

Associated with the property are 3 domestic dependencies of wood construction, with gable roofs, of indeterminate age and usage.

(Use Continuation Sheets)

Statement of Significance:

This cottage is architecturally undistinguished, has been altered, and does not appear to meet National Register Criteria for Evaluation

(Use Continuation Sheets)

Bibliographical References

(Use Continuation Sheets)

Form Prepared By: **Date:** July 2009

Name/Organization: David L. Taylor, Principal, Taylor and Taylor Associates, Inc.
Address: 9 Walnut Street
Brookville, PA 15825
Phone #: 814-849-4900 email: david@taylorandtaylorassociates.com

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination on departmental Federally Assisted Programs on the basis of race, color, national origin, age, or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, DC 20013-7127.

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM CONTINUATION SHEET

Central Hampshire County Historic Resource Survey, 2009

NAME_____ **Survey Site Number** 122