




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Horn Camp Road, c/ 1.6 mi. S of Grassy Lick Road	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 198	Site # (SHPO Only) <i>HM-0998</i>
Town or Community vic. Kirby	County Hampshire	Image No. 3598-3600	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1850	Style	
Exterior Siding/Materials Asbestos shingles	Roofing Material Standing-Seam Metal	Foundation Parged	
Property Use or Function Residence	UTM # 17/4339292/692309		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Sector, WV		
Part of What Survey/FR# Central Hampshire County Historic Resource Survey			

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This property anchors a farm which lies along a rural county road, northwest of the unincorporated village of Kirby and along the eastern foot of South Branch Mountain.	
Acres <u>none</u> Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
1 1/2 Stories Front Bays	
1 1/2-story vernacular residence of wood construction with a side-gable roof which is penetrated by paired dormers and extends over an original front porch which has been enclosed with a series of operable windows. Fenestration is flat-topped, without notable ornament. "No Trespassing" signage precludes close investigation.	
(Use Continuation Sheets)	
Alterations	
☒ Yes ☐ No	If yes, describe Porch enclosed; asbestos shingle siding installed
Additions	
☐ Yes ☒ No	If yes, describe Not apparent from right-of-way
Describe all Outbuildings	
A substantial gambrel roof barn with an extended gable is extended approximately 300 yards behind the house. Other smaller-scale agricultural dependencies are scattered nearby.	
(Use Continuation Sheets)	
Statement of Significance:	
This farmhouse is architecturally undistinguished, has been altered, and does not appear to meet National Register Criteria for Evaluation.	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By:	
Date: July 2009	
Name/Organization:	David L. Taylor, Principal. Taylor and Taylor Associates, Inc.
Address:	9 Walnut Street
	Brookville, PA 15825
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____

Survey Site Number _____

198

