



Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Horn Camp Road, N of Briar Lick Road	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 199	Site # (SHPO Only) HM-0999
Town or Community vic. Kirby	County Hampshire	Image No. 3601-3602	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1880	Style Gothic Revival; central-passage	
Exterior Siding/Materials German siding	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence, vacant	UTM # 17/4338915/692322		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Sector, WV Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This property lies along a rural county road, northwest of the unincorporated village of Kirby and along the eastern foot of South Branch Mountain.	
Acres <u>none</u> Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
2 Stories 3 Front Bays	
2-story vernacular residence of wood construction, with a side-gable roof and a locally distinctive centered pediment on the façade. L-shaped in plan, a non-historic addition has been built in the angle of the ell in the rear. Original exterior surfaces are finished in German siding and are penetrated by 6/6 windows on the façade. The center gable on the façade is finished in diagonal siding, with a pointed-arched window in the pediment. Extending across the façade is a shed-roofed porch, supported by turned posts. Building is deteriorated and appears vacant.	
(Use Continuation Sheets)	
Alterations ☒ Yes ☐ No If yes, describe Deterioration	
Additions ☒ Yes ☐ No If yes, describe As noted above	
Describe all Outbuildings	
Associated with the property are a series of domestic outbuildings of concrete block and wood construction, roofed with gable roofs and shed roofs.	
(Use Continuation Sheets)	
Statement of Significance:	
This house is architecturally undistinguished, has been altered, and is deteriorated, and does not appear to meet National Register Criteria for Evaluation.	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By:	
Date: July 2009	
Name/Organization:	
David L. Taylor. Principal. Taylor and Taylor Associates. Inc.	
Address:	
9 Walnut Street	
Brookville, PA 15825	
Phone #:	
814-849-4900 email: david@taylorandtaylorassociates.com	

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Survey Site Number 199

