



Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address N side Briar Lick Road, c. 1 mi. W of Kirby	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 206	Site # (SHPO Only) <i>HM-1006</i>
Town or Community vic. Kirby	County Hampshire	Image No. 3628, 3630-3632	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials Vinyl over weatherboard	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence	UTM # 17/4339780/694473		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name <i>Sector, WV</i> Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This farmhouse is located along a rural county road, between the unincorporated villages of Kirby and Horn Camp. Acres none Archaeological Artifacts Present	
Description of Buildings or Site (Original and Present)	
2 Stories 3 Front Bays 2-story vernacular residence of wood construction, with a three-bay first story and 2-bay second story, with the first story shielded by a hipped-roof porch supported by Doric columns. One gable end incorporates a 2-story bay window and a rearward-projecting 2-story ell extends from the back of the house. Fenestration is flat-topped, 1/1, without notable ornament. A red-brick chimney as well as a furnace flue penetrate the roof. (Use Continuation Sheets)	
Alterations	
☒ Yes ☐ No	If yes, describe Non-historic siding installed.
Additions	
☐ Yes ☒ No	If yes, describe Not evident from right-of-way.
Describe all Outbuildings	
Several agricultural and domestic dependencies are located in proximity to the house, including garages and a small barn of wood construction finished in vertical wood siding with doors on rollers. (Use Continuation Sheets)	
Statement of Significance:	
This farmhouse is architecturally undistinguished, has been altered, and does not appear to meet National Register Criteria for Evaluation. (Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By:	
Date: July 2009	
Name/Organization: David L. Taylor. Principal. Taylor and Taylor Associates. Inc.	
Address: 9 Walnut Street	
Brookville, PA 15825	
Phone #: 814-849-4900 email: david@taylorandtaylorassociates.com	

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Survey Site Number 706



