




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address S side Old Martinsburg Grade Road, W of SR 29	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 226	Site # (SHPO Only) <i>HM-1027</i>
Town or Community vic. Slanesville	County Hampshire	Image No. 3676-3677	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1850 (owner)	Style log	
Exterior Siding/Materials log, Vinyl over Weatherboard	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence	UTM # 17/4359071/709645		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name Hanging Rock, WV		
Part of What Survey/FR# Central Hampshire County Historic Resource Survey			

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address
Phone #	
Describe Setting	
This house is located in central Hampshire County, in a rural area northeast of the unincorporated village of Augusta.	Acres <u>none</u> Archaeological Artifacts Present
Description of Buildings or Site (Original and Present)	
_____ 2 _____ Stories _____ 7 _____ Front Bays	
2-story vernacular residence of wood construction, with a 7-bay first story and 4-bay second story. Building is originally of log, and is presently finished in non-historic siding. Building has a side-gabled roof with a centered chimney of stone. It was built in several sections, beginning with a 2-story log section which dates from ca. 1850, with additions dating from the 1890's. Extending across the entire façade is a shed-roofed porch finished in standing-seem metal, and supported by historic wood posts. Fenestration is flat-topped, with 6/6 sash, to which have been added non-historic fixed exterior shutters.	
(Use Continuation Sheets)	
Alterations ☒ Yes ☐ No	If yes, describe Non-historic siding installed at indeterminate time
Additions ☐ Yes ☐ No	If yes, describe
Describe all Outbuildings	
Several agricultural dependencies of varying age and construction are located close by.	
(Use Continuation Sheets)	
Statement of Significance:	
This log farmhouse has been altered and does not appear to meet National Register Criteria for Evaluation.	
(Use Continuation Sheets)	
Bibliographical References	
(Use Continuation Sheets)	
Form Prepared By:	Date: July 2009
Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.
Address:	9 Walnut Street Brookville, PA 15825
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____

Survey Site Number _____

226

