




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address Unnamed lane N of Frenches Station Road, N of Levels	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 276	Site # (SHPO Only) <i>HM-1079</i>
Town or Community vic. Levels	County Hampshire	Image No. 3784	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1900	Style central-passage	
Exterior Siding/Materials German siding	Roofing Material Standing-Seam Metal	Foundation Stone	
Property Use or Function Residence, vacant	UTM # 17/4375146/710281		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name <i>Oldtown, WV</i>		
	Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address								
Phone #									
Describe Setting									
This house is located in rural central Hampshire County north of the county seat of Romney and north of the unincorporated village of Levels.									
Acres none Archaeological Artifacts Present									
Description of Buildings or Site (Original and Present) 2 Stories 3 Front Bays									
Deteriorated 3-bay residence of wood construction with a side-gable roof and 1/1 and 2/2 windows. The front porch has collapsed and an addition on the right side appears in danger of collapse. The building is vacant and badly deteriorated.									
(Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;">If yes, describe</td> </tr> <tr> <td></td> <td></td> <td>Deterioration</td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe			Deterioration		
Alterations	☒ Yes ☐ No	If yes, describe							
		Deterioration							
<table style="width: 100%; border: none;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☐ Yes ☒ No </td> <td style="width: 75%;">If yes, describe</td> </tr> <tr> <td></td> <td></td> <td>Not evident from R/W</td> </tr> </table>		Additions	☐ Yes ☒ No	If yes, describe			Not evident from R/W		
Additions	☐ Yes ☒ No	If yes, describe							
		Not evident from R/W							
Describe all Outbuildings									
None									
(Use Continuation Sheets)									
Statement of Significance:									
This building is architecturally undistinguished, is seriously deteriorated, and does not appear to meet National Register Criteria for Evaluation.									
(Use Continuation Sheets)									
Bibliographical References									
(Use Continuation Sheets)									
<table style="width: 100%; border: none;"> <tr> <td style="width: 50%;">Form Prepared By:</td> <td style="width: 50%;">Date: July 2009</td> </tr> <tr> <td>Name/Organization:</td> <td>David L. Taylor. Principal. Taylor and Taylor Associates. Inc.</td> </tr> <tr> <td>Address:</td> <td>9 Walnut Street Brookville, PA 15825</td> </tr> <tr> <td>Phone #:</td> <td>814-849-4900 email: david@taylorandtaylorassociates.com</td> </tr> </table>		Form Prepared By:	Date: July 2009	Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.	Address:	9 Walnut Street Brookville, PA 15825	Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com
Form Prepared By:	Date: July 2009								
Name/Organization:	David L. Taylor. Principal. Taylor and Taylor Associates. Inc.								
Address:	9 Walnut Street Brookville, PA 15825								
Phone #:	814-849-4900 email: david@taylorandtaylorassociates.com								

West Virginia Division of Culture and History
State Historic Preservation Office