




Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address E side Springfield- Green Spring Road	Common/Historic Property Name/ Both	Field Survey # Central Hampshire County Survey No. 347	Site # (SHPO Only) <i>HM-1153</i>
Town or Community vic. Green Spring	County Hampshire	Image No. 3893-3894	NR Listed Date n/a
Architect/Builder Unidentified	Date of Construction c. 1920	Style Craftsman	
Exterior Siding/Materials Vinyl over weatherboard	Roofing Material Asphalt Shingles	Foundation Concrete Block	
Property Use or Function Residence	UTM # 17/4376404/703143		
Survey Organization and Date Taylor and Taylor Associates, for the Hampshire County Historic Landmarks Commission, 2008-2009	Quadrangle Name <i>Patterson Creek MD, W 0</i> Part of What Survey/FR# Central Hampshire County Historic Resource Survey		

Sketch Map of Property
or Attach Copy of USGS Map See Survey Report

Property Owners	Owner's Mailing Address			
Phone #				
Describe Setting				
This house is located in rural north-central Hampshire County south of the unincorporated village of Green Spring, whose northern boundary is defined by a substantial railyard.				
Acres none Archaeological Artifacts Present				
Description of Buildings or Site (Original and Present)				
1½ Stories 3 Front Bays				
1½-story Craftsman-style Bungalow of wood construction, with a side gable roof and gable dormers front and rear. The roof extends beyond the plain of the building to shield a recessed front porch which is supported by wood piers which rest on bases of cobblestone; the porch is enclosed within a solid wood balustrade. Fenestration is generally flat-topped, with replacement sash and exterior fixed shutters. A diamond-paned single light window is on the side elevation, likely opening into a stairwell inside. The original back porch has been enclosed.				
(Use Continuation Sheets)				
<table style="width: 100%;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe Non-historic siding installed at indeterminate time </td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe Non-historic siding installed at indeterminate time
Alterations	☒ Yes ☐ No	If yes, describe Non-historic siding installed at indeterminate time		
<table style="width: 100%;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☐ Yes ☒ No </td> <td style="width: 75%;"> If yes, describe Not evident from R/W. </td> </tr> </table>		Additions	☐ Yes ☒ No	If yes, describe Not evident from R/W.
Additions	☐ Yes ☒ No	If yes, describe Not evident from R/W.		
Describe all Outbuildings				
Associated with the property is a 1-story gable-end-oriented garage of wood construction.				
(Use Continuation Sheets)				
Statement of Significance:				
This house is architecturally undistinguished, has been altered, and does not appear to meet National Register Criteria for Evaluation.				
(Use Continuation Sheets)				
Bibliographical References				
(Use Continuation Sheets)				
Form Prepared By:				
Date: July 2009				
Name/Organization:				
David L. Taylor. Principal. Taylor and Taylor Associates, Inc.				
Address:				
9 Walnut Street				
Brookville, PA 15825				
Phone #:				
814-849-4900 email: david@taylorandtaylorassociates.com				

West Virginia Division of Culture and History
State Historic Preservation Office

**WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM
CONTINUATION SHEET**

Central Hampshire County Historic Resource Survey, 2009

NAME _____ Survey Site Number 347

