Internal Rating: _____

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address Horn Camp Rd. (CR 10-3)	**Common/Historic Name/Both** **X** **O** **O** House	**Field Survey #** HM-1175	**Site # *(SHPO Only)***
Town or Community	**County** Hampshire	**Negative No.**	**NR Listed Date**
Architect/Builder	**Date of Construction** ca. 1900	**Style** I-house	
Exterior Siding/Materials Vinyl	**Roofing Material** Standing-seam metal	**Foundation** Concrete-block	
Property Use or Function **Residence** **X** **Commercial** **O** **Other** **O**	**UTM#** NAD83 / UTM zone 17N E 694040.785 N 4337739.596		
Survey Organization & Date The Louis Berger Group, Inc. 6/15/2010	**Quadrangle Name** Sector, WV **Part of What Survey/FR#** PATH 765 kV Transmission Line FR# 08-822-Multi		

Sketch Map of Property
Or Attach Copy of USGS Map

Site No.

Present Owners	Owners Mailing Address
Phone #	

Describe Setting

The property is located on the west side of Horn Camp Road on a level grassy lot with mature trees.

_____ **Acres**

_____ **Archaeological Artifacts Present**

Description of Building or Site (Original and Present) ____2____ **Stories** ____3____ **Front Bays**

The two-story, three-bay I-house features a concrete-block foundation, vinyl siding, and a side-gable roof clad in standing-seam metal. The three-bay front (east) elevation features a centered door flanked by one-over-one vinyl replacement windows. The façade is sheltered by a rebuilt shed-roof porch supported by replacement metal poles. A one-story shed-roof concrete-block constructed lean-to is located on the rear (west) elevation. A bay window and an exterior concrete-block chimney are located on the south gable end.

(Use Continuation Sheets)

Alterations [X] **Yes** [ ] **No** **If yes, describe** Replacement windows and siding, modifications to the front porch

Additions [ ] **Yes** [X] **No** **If yes, describe**

Describe All Outbuildings

Two secondary resources sit west of the dwelling. One is a front-gabled spring house clad in wood siding. The other is a front-gabled outbuilding clad in wood siding. Both have galvanized, standing-seam roofing with open eaves and exposed rafters.

(Use Continuation Sheets)

Statement of Significance

It is the opinion of the surveyor that this ca. 1900 dwelling lacks sufficient architectural and historical significance and is not eligible for inclusion in the National Register. It does not possess characteristics of demonstrable significance with respect to design, construction or use of materials (Criterion C) and has been altered with replacement siding and windows and modifications to the front porch. As such, its architectural integrity has been compromised. It does not appear to be associated with significant broad patterns, events or persons (Criteria A and B). It has not yielded, nor is it likely to yield, information important to history or prehistory (Criterion D).

(Use Continuation Sheets)

Bibliographical References

(Use Continuation Sheets)

Form Prepared By: Stephanie Jacobe **Date:** 3/1/2011

Name/Organization: The Louis Berger Group, Inc.

Address: 801 E. Main Street, Richmond, VA 23219

Phone #: (804) 228-4300

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.

WEST VIRGINIA HISTORIC PROPERTY FORM
CONTINUATION SHEET

NAME____House, Horn Camp Rd._____ **SITE#**____HM-1175_____

WEST VIRGINIA HISTORIC PROPERTY FORM
CONTINUATION SHEET

NAME House, Horn Camp Rd. (CR 10-3) **SITE#** HM-1175