



WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Street Address U.S. 220	Common/Historic Name/Both ☐ ☐ ☐	Field Survey # HM-1183	Site # (SHPO Only) see also HM-0091-0007
Town or Community Purgitsville vicinity	County Hampshire	Negative No. WV_HampshireCounty_HM-1183.tif	NR Listed Date
Architect/Builder unknown	Date of Construction Circa 1800	Style I-House	
Exterior Siding/Materials Wood	Roofing Material Metal	Foundation Stone	
Property Use or Function Residence ☒ Commercial ☐ Other ☐	NAD83 UTM# 17S 0679738E/ 4344180N		
Survey Organization & Date Rasmussen and Rasmussen Fall 2010	Quadrangle Name Old Fields		
	Part of What Survey Hampshire County, Phase III		

Sketch Map of Property
Or Attach Copy of USGS Map

Site No.

Present Owners Phone #	Owners Mailing Address
Describe Setting Small lot located below grade ≤1 Acres ____ Artifacts Present	
Description of Building or Site (Original and Present) 2 Stories 3 Front Bays Center hall I-house with massive stone chimney on the left gable end. Two/2 double hung sash that are probably original. Deep window reveals and lapped siding with corner boards that probably covers log construction. Shed roof front porch with plain wood supports.	
<i>(Use Continuation Sheets)</i>	
Alterations ☐ Yes ☒ No	
Additions ☐ Yes ☒ No	
Describe All Outbuildings Small barn of wood with metal roof <i>(Use Continuation Sheets)</i>	
Statement of Significance Two resources retain their architectural integrity <i>(Use Continuation Sheets)</i>	
Bibliographical References <i>(Use Continuation Sheets)</i>	
Form Prepared By: Barbara Rasmussen Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652 Date: September 22, 2010	



[West Virginia Division of Culture and History](http://www.wvculture.org)
 State Historic Preservation Office

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.



WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

see also HM-1183

Street Address Route 220	Common/Historic Name/Both ☒ ☐ ☐	Field Survey # 0007	Site # (SHPO Only) HM-0091-0007
Town or Community Purgitsville, WV	County Hampshire	Negative No.	NR Listed Date
Architect/Builder Unknown	Date of Construction circa 1900 s	Style (SHPO Only) I- House	
Exterior Siding / Materials Horizontal boards Clapboard	Roofing Material Sheet metal	Foundation Cut stone	
Property Use or Function Residential	UTM Zone 17 NAD 1927 Easting 679,723 Northing 4,343,960		
	Quadrangle Name Old Fields		
Survey Organization & Date WVDOH November 6, 2000	Part of What Survey / FR# Moorefield to Junction # U314-220-1.54		



GMV

HM-0091-0007

Site No.

Name:

Survey #:

Survey / FR#: Moorefield to Junction # U314-220-1.54

Hm-0091-0007

Present Owners Unknown	Owners Mailing Address Unknown				
Describe Setting Unknown -- <1 Acres ☐ Archaeological Artifacts Present Rural town along a major county route. Mostly farms and isolated houses, no commercial structures. The proposed project will realign the horizontal and vertical alignment of Route 220 from Purgitsville, West Virginia to ½ mile south.					
Description of Buildings or Site (Original and Present) 1 1/2 Stories 3 Front Bays Side gabled I house structure with rabbeted horizontal boards and a rough cut stone foundation. Has an exterior gabled rough cut stone chimney and a sheet metal roof.					
Alterations ☒ Yes ☐ No If yes, describe Roof and new windows on top floor of structure.					
Additions ☒ Yes ☐ No If yes, describe One addition in the rear of a side gabled structure with a concrete block foundation.					
Describe All Outbuildings One front gabled horizontal board shed on the premises. Across Route 220, also used as a shed is a 1 1/2 story side gabled one bay structure with multipaned double hung windows. It has a dropped roof addition on its rear. Composition shingle siding.					
Statement of Significance: See Continuation Sheet					
Bibliographical References McAlester, V. and L. 1984. A Field Guide to American Houses. NY: Alfred A. Knopf					
<table border="0" style="width: 100%;"> <tr> <td style="width: 60%;">Form Prepared By:</td> <td style="width: 40%;">Date: February 16, 2001</td> </tr> <tr> <td colspan="2"> Name/Organization: Chandra Inglis Address: WV Division of Highways Capitol Complex Building 5, Rm. 463 Charleston, WV 25305 Phone #: 558-2885 </td> </tr> </table>		Form Prepared By:	Date: February 16, 2001	Name/Organization: Chandra Inglis Address: WV Division of Highways Capitol Complex Building 5, Rm. 463 Charleston, WV 25305 Phone #: 558-2885	
Form Prepared By:	Date: February 16, 2001				
Name/Organization: Chandra Inglis Address: WV Division of Highways Capitol Complex Building 5, Rm. 463 Charleston, WV 25305 Phone #: 558-2885					

WEST VIRGINIA HISTORIC PROPERTY FORM CONTINUATION SHEET

Name:

Survey Number:

Project / FR#: Moorefield to Junction # U314-220-1.54

As an individual structure, the // does not have an important link with events or trends that have made a significant contribution to the broad patterns of our history. As an individual structure it does not meet National Register Criteria A of association with events at the National, Regional, or Local level.

It is not eligible for the National Register because it is not known to have been associated with the productive period of some notable person's life, nor has it been associated for any length of time with such a person, nor is it the best representation of such a person's historic contribution (NRHP Criterion B).

This structure does not represent the work of a master or possess high artistic values. While it embodies the characteristics of an architectural period, they are of commonplace type and method of construction, and this is not an important example of these building practices. Its workmanship is not remarkable. NRHP Criterion C is not met by this structure.

This structure is not likely to have important information that will contribute to our understanding of human history or prehistory. Construction appears to have utilized known techniques, tools, and materials. The potential for information is trivial, so NRHP Criterion D is not met.