



WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

Address Rt. 220/28	Common/Historic Name/Both O O O	Field Survey # HM-1192	Site # (SHPO Only) see also HM-0090-0002
Town or Community Purgitsville vicinity	County Hampshire	Negative No. WV_Hampshire County_HM-1192.tif	NR Listed Date
Architect/Builder Unknown	Date of Construction Circa 1960	Style Cross gable	
Exterior Siding/Materials Aluminum	Roofing Material Metal	Foundation Obscured	
Property Use or Function Residence ☒ Commercial ☐ Other ☐	NAD 83 UTM# 17S 0679380E/4345940N		
Survey Organization & Date Rasmussen and Rasmussen Fall 2010	Quadrangle Name Old Fields		
	Part of What Survey Hampshire County III		

Sketch Map of Property
Or Attach Copy of USGS Map

Site No.

Present Owners Phone #	Owners Mailing Address 			
Describe Setting Next to a church on a small lot close to the road >1 ____ Acres ____ Artifacts Present				
Description of Building or Site (Original and Present) 2 Stories ____ 2 ____ Front Bays Large cross-gable house with replacement sliding windows, bay window, raised rear wing. <i>(Use Continuation Sheets)</i>				
<table style="width: 100%;"> <tr> <td style="width: 15%;">Alterations</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> If yes, describe reconfigured footprint, aluminum siding, replacement windows </td> </tr> </table>		Alterations	☒ Yes ☐ No	If yes, describe reconfigured footprint, aluminum siding, replacement windows
Alterations	☒ Yes ☐ No	If yes, describe reconfigured footprint, aluminum siding, replacement windows		
<table style="width: 100%;"> <tr> <td style="width: 15%;">Additions</td> <td style="width: 10%;"> ☒ Yes ☐ No </td> <td style="width: 75%;"> Rear wing </td> </tr> </table>		Additions	☒ Yes ☐ No	Rear wing
Additions	☒ Yes ☐ No	Rear wing		
Describe All Outbuildings None <i>(Use Continuation Sheets)</i>				
Statement of Significance Loss of historic integrity <i>(Use Continuation Sheets)</i>				
Bibliographical References <i>(Use Continuation Sheets)</i>				
Form Prepared By: Barbara Rasmussen Date: November 10, 2010 Address: 224 Wilson Avenue, Morgantown, WV 26501 Phone #: (304) 292 7652				



West Virginia Division of Culture and History
 State Historic Preservation Office

This program receives federal funds from the National Park Service. Regulations of the U. S. Department of the Interior prohibit unlawful discrimination in department Federally Assisted Programs on the basis of race, color, national origin, age or handicap. Any person who believes he or she has been discriminated against in any program, activity, or facility operated by a recipient of Federal Assistance should write to: Director, Equal Opportunity Program, U.S. Department of the Interior, National Park Service, P.O. Box 37127, Washington, D.C. 20013-7127.

Internal Rating: NE

WEST VIRGINIA HISTORIC PROPERTY INVENTORY FORM

see also HM-1192

Street Address US Route 220	Common/Historic Name/Both ☒ Structure 2 ☐ ☐	Field Survey # 0002	Site # (SHPO Only) HM-0090-0002
Town or Community Purgitsville	County Hampshire	Negative No.	NR Listed Date
Architect/Builder Unknown	Date of Construction circa 1915	Style (SHPO Only) BUNGALOW	
Exterior Siding / Materials Vinyl siding Construction material: timber	Roofing Material Standing seam tin	Foundation Cinder block	
Property Use or Function Residential	UTM Zone 17 NAD 1927 Easting 679,373 Northing 4,345,733	Photograph (2" x 3" Contact)	
Survey Organization & Date WVDOH September 14, 2000	Quadrangle Name Old Fields		
	Part of What Survey / FR#		



GM✓

HM-0090-0002

Site No.

Name: Structure 2
 Survey #:
 Survey / FR#:

Am - 0090-0002

Present Owners Unknown	Owners Mailing Address Unknown /
Describe Setting <1 Acres ☐ Archaeological Artifacts Present The house is situated along Route 220, next to Marvin Chapel. It is approximatly .5miles from the center of Purgitsville.	
Description of Buildings or Site (Original and Present) 1 Stories 1 Front Bays This structure was built in the Craftsman style. It has a simple hipped roof with a cross cable dormer that has a bulls eye window. The windows are double hung with wooden sills. There is a slope placed chimney that is a stove pipe incased in cinder blocks. On the front of the building is a porch that has an extended roof.	
Alterations ☒ Yes ☐ No If yes, describe The addition of vinyl siding and more modern roofing materials. One third of the front porch has been inclosed with plywood and painted over.	
Additions ☐ Yes ☒ No If yes, describe	
Describe All Outbuildings none	
Statement of Significance: See Continuation Sheet	
Bibliographical References McAlester, V. and L. 1984. A Field Guide to American Houses. NY: Alfred A. Knopf	
Form Prepared By: Date: September 14, 2000 Name/Organization: Chandra Inglis Address: WV Division of Highways Capitol Complex Building 5, Rm. 463 Charleston, WV 25305 Phone #: 558-2885	

WEST VIRGINIA HISTORIC PROPERTY FORM CONTINUATION SHEET

Name: Structure 2
Survey Number:
Project / FR#:

As an individual structure, the house does not have an important link with events or trends that have made a significant contribution to the broad patterns of our history. As an individual structure it does not meet National Register Criteria A of association with events at the National, Regional, or Local level.

It is not eligible for the National Register because it is not known to have been associated with the productive period of some notable person's life, nor has it been associated for any length of time with such a person, nor is it the best representation of such a person's historic contribution (NRHP Criterion B).

This structure does not represent the work of a master or possess high artistic values. While it embodies the characteristics of an architectural period, they are of commonplace type and method of construction, and this is not an important example of these building practices. Its workmanship is not remarkable. NRHP Criterion C is not met by this structure.

This structure is not likely to have important information that will contribute to our understanding of human history or prehistory. Construction appears to have utilized known techniques, tools, and materials. The potential for information is trivial, so NRHP Criterion D is not met.