









COUNTY: UPSH

Survey Region: \_\_\_\_\_

Planning District: \_\_\_\_

Sanks District

a. Exterior Fabric	b. Structural System		c. Roofing Material
stone	masonry		wood
brick	frameball(	90n	metal
concrete	log		slate
stucco	. шетат	× * `	tile
weatherboard	other		asphalt
clapboard			composition
board & batten	- C	ontinuous	
. shingle	foundation		<u>shingle replacement</u>
with rolled brick siding.			
Sturing.			
d. Associated Structures (use/type):		e. Integrity (include	dates):
outbuildings		_ original site/reloc	aled <u>original building on</u>
dependencies cellar attach	ed to side		with many houses in this
Porch			the exterior surface has
			ered with new coverings
other			
		noncho	os on sido
		— porches on side	
		No ext	ernal chimneys evident
f. Condition:	g. Threats:		
	None.		·
excellent	-		
good X			
fair	-		
deteriorated			
abandoned	_		
•	•		
CICNIFICANCE ( 11:: 1 .k : f			
SIGNIFICANCE (use additional sheet if necessary):		1-77 1/27	and the second second
a. Architect/Builder/Engineer:			settled here in the
-Gideon Wilson	mid 1860	)'s and opera	ited a grist and saw
-GIUCUII WIISUII	mill unt	il thev were	e destroyed by fire, 1890.
b. Style/Period: Douple Pile			fice was housed here for
Simple country style			Tice was noused here for
c. Date(s): with 4 rooms down	a period	d of years.	
c., 1860's			
0., 2000 3			
for a second control of			
BIBLIOGRAPHY:			
utright, W.B. "History of U	nshur County	(IICPL)	
hone interview with Dhullia	7ickofooco /	Chostansage	ighton of Cidoon Wilcom\10
hone interview with Phyllis	ZICKETOOSE (	ureacyrandau	Murren of Glacon Milson)10

12. FORM PREPARED BY William Noel W. Tenney Date Autumn, 1984

a. Address P.O. Box 2082, Buckhangen, W.V.A. 26201

b. Organization Upshur County Historical Society